



**BANK of ZAMBIA**

**Tel: 0211 399300**

**P.O BOX 30080**

26<sup>th</sup> February 2021

**ADDENDUM NUMBER 2**

**TO : ALL BIDDERS**

**IFB NO. BOZ/PMS/ONB/02/2021 – TENDER FOR THE REFURBISHMENT OF THE 4<sup>TH</sup> FLOOR OF THE ANNEX BUILDING AT BANK OF ZAMBIA HEAD OFFICE**

---

Reference is made to the above captioned matter. We have received a query from a prospective bidder. The queries, with our response, have been reproduced below.

**Query 1**

Under Demolitions, the Architects spoke of a door at the server room that needs to be taken down and opening blocked up, this item is not in the Boq.

**Response**

Pages 42 of the BOQ, has indicated the door at the server room that needs to be taken down (removal of doorframes).

Pages 44 of the BOQ, has indicated the blockwork. Item C is referring to blockwork

**Query 2**

The drawings show that there is blockwork to be done, this hasn't been provided for in the BOQ.

**Response**

Page 44, item C refers to blockwork in the BOQ.

**Query 3**

Under Electricals, the Architects spoke of 600 x 600 Led panels which have not been provided for in the BOQ.

**Response**

Page 72, refers to light fitting Type A (Item H on BOQ).

**Query 4**

The client should provide us with a schedule with pictures for the furniture, if possible also suggest the preferred suppliers.

**Response**

Bidders may ignore this requirement. The Bank will procure this item separately.

**Query 5**

It was clear at the site meeting that the Bills were not complete, we are therefore requesting for the PDF Copy of the Bills.

**Response**

The PDF version is attached for reference.

Yours Faithfully

*For and on behalf of Bank of Zambia*

A handwritten signature in black ink, consisting of a circular flourish on the left, followed by a horizontal line with a double vertical bar in the middle, and a final flourish on the right.

**EVANS K. LUNETTA  
DIRECTOR – PROCUREMENT AND MAINTENANCE SERVICES.**